



**THE MAHARAJA SAYAJIRAO UNIVERSITY OF BARODA**  
(Construction Division)

Telephone: 2795512

BARODA - 390 002

University Engineer

Date: 17-07-19

No. CD /

**INSPECTION REPORT FOR DELHI PUBLIC SCHOOL (KALALI)**

Name of property: **DELHI PUBLIC SCHOOL (KALALI)**

Location : R.S. No: 511/2/P,  
Block No: 420/P,  
Village Kalali Dist. Vadodara.

Name of occupier : **DELHI PUBLIC SCHOOL**

Type of structure: R.C.C

Date of Inspection: 17<sup>th</sup> July 2019

Purpose of Inspection: To comply Circular No: CBSC/AFF/430053/EX-00750-1920/2019 dated 28<sup>th</sup> June 2019 Issued by Central Board of Secondary Education.

I have inspected the site on dated 17<sup>th</sup> July 2019 as requested by the principal **DELHI PUBLIC SCHOOL (KALALI)**.

The property is being used as a school building since 16 years by Delhi Public School.

*[Signature]*  
Principal  
Delhi Public School  
Vadodara.





*[Signature]*  
12/7

The property is situated in R.S. No: 511/2/P, Block No: 420/P, at village Kalali Dist. Vadodara. The property consist of basement in some part, ground floor, first floor, Second floor and part third floor. The property was constructed before 16 years. It was constructed as a R.C.C frame structure containing R.C.C Foundation, Columns, Beams, Slab etc.

The following observation have been marked as per Circular No: 28/2004 dated 26<sup>th</sup> July 2004 issued by Central Board of Secondary Education, during inspection.

| Sr.No | Remark  | Observation   |
|-------|---|---|
| 1     | Does school have any temporary structure or any class room/ other room which has thatched roofing and which is inflammable? | No temporary structure or class room.   |
| 2     | Is School situated in old or dilapidated buildings?   | The school building is a newly constructed RCC structure.   |
| 3     | Has the building been certified as safe for housing the students by the local authorities?                                  | Yes   |
| 4     | Are there any cracks in the school structures and are steps being taken to repair?  | No cracks observed.   |
| 5     | Is school located near railway track?   | No  |
| 6     | Is school is situated in the earthquake risk zone.  | No The school building structure is structurally designed by considering the appropriate earth quake zone as per IS 1893. |

  
Principal  
Delhi Public School  
Vadodara.

  
12/7



STAFF STATEMENT

| Name of Teacher | DOB | Emp. No. | Qualification | SUBJECT TAUGHT | CLASSES TAUGHT | DATE OF JOINING | Date of Completion | SCALE |
|-----------------|-----|----------|---------------|----------------|----------------|-----------------|--------------------|-------|
| 7               |     |          |               |                |                |                 |                    |       |
| 8               |     |          |               |                |                |                 |                    |       |
| 9               |     |          |               |                |                |                 |                    |       |
| 10              |     |          |               |                |                |                 |                    |       |

Have necessary steps been taken during construction of the building for earthquake safety for the building? Yes

How safe is your construction to face a natural disaster of this kind? The building is structurally designed as per relevant IS Codes applicable for safety against natural disaster.

What emergency steps are in place in the school for disaster preparedness? Emergency Alarms and contact with disaster management authority of government.


Is there a trained disaster management group available in school for initial response? Or is school in touch with the local disaster management authorities for training and retraining them? The school has no such type of group in the school premises but the school is having in touch with local disaster management authorities.

By the inspection of the site and considering the above points, I am of the opinion that presently the building is stable and serviceable. The building remain continue to utilize as a school building. This opinion is given only on the basis of visual observation. No specific tests are carried out.


The above inspection report is given on the basis of the personal site visit and the information provided by the school.

Date:

Place: Vadodara

  
University Engineer,  
M. S. University of Baroda



  
Principal  
Delhi Public School  
Vadodara.

